CoreSysServices v3.2

Release Notes





Microsemi Corporate Headquarters

One Enterprise, Aliso Viejo, CA 92656 USA Within the USA: +1 (800) 713-4113

Outside the USA: +1 (949) 380-6100 Sales: +1 (949) 380-6136 Fax: +1 (949) 215-4996

E-mail: sales.support@microsemi.com www.microsemi.com

© 2018 Microsemi Corporation. All rights reserved. Microsemi and the Microsemi logo are trademarks of Microsemi Corporation. All other trademarks and service marks are the property of their respective owners.

Microsemi makes no warranty, representation, or guarantee regarding the information contained herein or the suitability of its products and services for any particular purpose, nor does Microsemi assume any liability whatsoever arising out of the application or use of any product or circuit. The products sold hereunder and any other products sold by Microsemi have been subject to limited testing and should not be used in conjunction with mission-critical equipment or applications. Any performance specifications are believed to be reliable but are not verified, and Buyer must conduct and complete all performance and other testing of the products, alone and together with, or installed in, any end-products. Buyer shall not rely on any data and performance specifications or parameters provided by Microsemi. It is the Buyer's responsibility to independently determine suitability of any products and to test and verify the same. The information provided by Microsemi hereunder is provided "as is, where is" and with all faults, and the entire risk associated with such information is entirely with the Buyer. Microsemi does not grant, explicitly or implicitly, to any party any patent rights, licenses, or any other IP rights, whether with regard to such information itself or anything described by such information. Information provided in this document is proprietary to Microsemi, and Microsemi reserves the right to make any changes to the information in this document or to any products and services at any time without notice.

About Microsemi

Microsemi Corporation (Nasdaq: MSCC) offers a comprehensive portfolio of semiconductor and system solutions for aerospace & defense, communications, data center and industrial markets. Products include high-performance and radiation-hardened analog mixed-signal integrated circuits, FPGAs, SoCs and ASICs; power management products; timing and synchronization devices and precise time solutions, setting the world's standard for time; voice processing devices; RF solutions; discrete components; enterprise storage and communication solutions, security technologies and scalable anti-tamper products; Ethernet solutions; Power-over-Ethernet ICs and midspans; as well as custom design capabilities and services. Microsemi is headquartered in Aliso Viejo, Calif., and has approximately 4,800 employees globally. Learn more at www.microsemi.com.



Contents

Revisi	on History	. 1
1.1	Revision 4	
1.2	Revision 3	1
1.3	Revision 2	1
1.4	Revision 1	1
CoreS	sysServices Release Notes	. 2
2.1	Key Features	
2.2	Delivery Types	2
	2.2.1 ŘŤL	
2.3	Supported Families	2
2.4	Supported Tool Flows	2
2.5	Installation Instructions	2
2.6	Documentation	3
2.7	Supported Test Environments	3
2.8	Discontinued Features and Devices	
2.9	Known Issues and Workarounds	3
2.10	Resolved Issues in the v3.2 Release	3
2.11	Resolved Issues in the v3.1 Release	3
2.12	Resolved Issues in the v3.0 Release	3
	1.1 1.2 1.3 1.4 CoreS 2.1 2.2 2.3 2.4 2.5 2.6 2.7 2.8 2.9 2.10 2.11	1.2 Revision 3 1.3 Revision 2 1.4 Revision 1 CoreSysServices Release Notes 2.1 Key Features 2.2 Delivery Types 2.2.1 RTL 2.3 Supported Families 2.4 Supported Tool Flows 2.5 Installation Instructions 2.6 Documentation 2.7 Supported Test Environments 2.8 Discontinued Features and Devices 2.9 Known Issues and Workarounds 2.10 Resolved Issues in the v3.2 Release 2.11 Resolved Issues in the v3.1 Release



Tables

Table 1	Resolved software action request (SARs) in CoreSysServices v3.2 Release	j
Table 2	Resolved software action request (SARs) in CoreSysServices v3.1 Release	j
Table 3	Resolved software action request (SARs) in CoreSysServices v3.0 Release	,

Revision 4 iv



1 Revision History

1.1 Revision 4

Updated for CoreSysServices v3.2.

1.2 Revision 3

Updated for CoreSysServices v3.1.

1.3 Revision 2

Updated for CoreSysServices v3.0.

1.4 Revision 1

Revision 1.0 was the first publication of this document. Created for CoreSysServices v2.0.



2 CoreSysServices Release Notes

These release notes accompany the production release of CoreSysServices v3.2. This document provides details about the features and enhancements, system requirements, supported families, implementations, and known limitations and workarounds.

2.1 Key Features

CoreSysServices is a highly configurable core and has the following features:

- Provides the following system services:
 - Device and design information services
 - Cryptographic services
 - Differential Power Analysis (DPA)-Resistant Key-Tree services
 - Non-deterministic random bit generator (NRBG) services
 - · Zeroization service
 - · Digest Check service
 - Programming Service: In-application programming (IAP)
 - · Physically Uncloneable function (PUF) Service
 - Tamper Control and Detect Service
 - · Elliptic Curve Services
 - · Asynchronous Messaging Service
 - · Flash Freeze Service
- Provides shared request user interface for all system services
- Provides shared response user interface for all system services
- Provides advanced high-performance bus (AHB)-Lite master interface to the fabric interface controller (FIC)
- · Provides support to high priority system services over on-going Low priority services

2.2 Delivery Types

No license is required to use CoreSysServices.

2.2.1 RTL

Complete RTL source code is provided for the core.

2.3 Supported Families

- SmartFusion[®]2
- IGLOO®2

2.4 Supported Tool Flows

- CoreSysServices v3.2 requires Libero® System-on-Chip (SoC) software v11.0 or later.
- Supports Windows and Linux operating systems.

2.5 Installation Instructions

The CoreSysServices CPZ file must be installed into Libero software. This is done automatically through the Catalog update function in Libero, or the CPZ file can be manually added using the Add Core catalog feature. Once the CPZ file is installed in Libero, the core can be configured, generated, and instantiated within SmartDesign for inclusion in the Libero project. Refer, *Libero SoC online help* for instructions on core installation, licensing, and general use.



2.6 Documentation

This release contains a copy of the CoreSysServices Handbook. This handbook describes the core functionality, gives step-by-step instructions on how to synthesize, and place-and-route this core, and also provides implementation suggestions.

For updates and additional information about the software, devices, and hardware, visit the Intellectual Property pages on the Microsemi web site at: www.microsemi.com/soc.

2.7 Supported Test Environments

The following test environment is supported:

- Verilog user testbench
- · Verilog full verification testbench

2.8 Discontinued Features and Devices

There are no discontinued features or devices in the CoreSysServices v3.2 release.

2.9 Known Issues and Workarounds

VHDL Testbench is not supported. There are no other known issues or workarounds in CoreSysServices v3.2 release.

2.10 Resolved Issues in the v3.2 Release

Table 1 • Resolved software action request (SARs) in CoreSysServices v3.2 Release

SAR	Description
76145	The description of IAP operation in SERV_OPTIONS_MODE is updated in Handbook.

2.11 Resolved Issues in the v3.1 Release

Table 2 • Resolved software action request (SARs) in CoreSysServices v3.1 Release

SAR	Description
63573	IAP Verify is not working
63326	Request for timing diagrams for different services.

2.12 Resolved Issues in the v3.0 Release

Table 3 • Resolved software action request (SARs) in CoreSysServices v3.0 Release

Description
Zeroization service SERV_ZERI_EN is not working.
Fabric digest check is not working.
Clarify MSS/HPMS and add device support table to HB.
Incorrect Response code (SERV_STATUS_RESP) is read in Error Force Response and Unrecognized response scenarios.
PoR service is not working.
CoreSysService is hanging while performing device in services after Fabric Digest.



Table 3 • Resolved software action request (SARs) in CoreSysServices v3.0 Release

SAR	Description
53201	SERV_CMDBYTE_REQ is typed as SERV_CMDBYTE under timing diagram.