



TimeCraft Network Element Craft Software System Release Notice

INTRODUCTION

This System Release Notice (SRN) describes the new features of Microchip's TimeCraft Network Element Craft Software, version 2.6.5a. It includes system requirements, new platform features, resolved and known issues, supported network elements for Microchip products, install, uninstall, and firmware upgrade procedures, and technical support contact information. In addition to this release notice, the TimeCraft Release 2.6.2 User's Guide (PN 098-00641-262) is located in the downloadable zip file.

Precautions

Please read [Installing TimeCraft Application](#) and [Uninstalling TimeCraft Application](#) before attempting to install version 2.6.5a release.

- If earlier versions of TimeCraft (2.2 or earlier) exists on the target system, the user should backup the connections and properties files and then uninstall the existing installation. After uninstallation of the earlier version, TimeCraft 2.6.5a can be installed as a full installation.
- If no installation of TimeCraft exists, the setup installs TimeCraft 2.6.5a.
- If TimeCraft 2.3, 2.3.1, 2.4, 2.5, 2.6, 2.6.1, 2.6.2, 2.6.3, 2.6.4, or 2.6.5 exists, then uninstall older version and install 2.6.5a after removing the residual files from system.

Notes

Use the following steps to backup connections:

1. Open Windows Explorer and browse to the TimeCraft installed location (Default is "C:\Program Files\Symmet-ricom\TimeCraft").
2. Copy the connections folder to another location.
3. Uninstall earlier version of TimeCraft.
4. Install TimeCraft 2.6.5a.
5. Copy the Connections folder to the TimeCraft installed location (Default is "C:\Program Files\Microsemi\Time-Craft" on 32 bit OS, and "C:\Program Files (x86)\Microsemi\TimeCraft" in case of 64 bit OS).

To migrate the connections created in TimeCraft 2.2 and earlier version, you can use Windows Explorer to create the directories with the following steps:

1. Open Windows Explorer and browse to the Connections folder in the TimeCraft installation location (Default is "C:\Program Files\Symmetricom\TimeCraft").
2. Create sub folders to reflect site/location as desired.
3. Move the connection files in the connection folder created in TimeCraft 2.2 or earlier to the created sub folders.

To verify that the connections were properly created, start the TimeCraft application, select the **Connection** menu item and click **Open Connection**. The connections should appear in the folder trees.

SYSTEM REQUIREMENTS

The following are the recommended minimal requirements to support this product:

- Operating Systems:
 - Windows® XP
 - Windows 7 32-bit and 64-bit
 - Windows 8 64-bit
- 1 GHz Pentium Processor
- 512 MB RAM
- 1 GB Free Disk Space
- 8x CD-ROM drive

SVGA display (minimum screen resolution set at 1280 x 1024)

NEW PLATFORM FEATURES

The following changes and additions were made in this release.

SSU 2000 7.3.1 connectivity

RESOLVED ISSUES

There are no resolved issues with this release.

Contents

Introduction	1
System Requirements	2
New Platform Features	2
Resolved Issues	2
1.0 Known Issues and Workaround	4
2.0 Supported Network Elements—Support Matrix	6
3.0 Installing TimeCraft Application	7
4.0 Upgrading TimeCraft Application 2.3/2.4/2.5 or 2.6 to TimeCraft 2.6.5	12
5.0 Uninstalling TimeCraft Application	14
6.0 Removing SynCraft / TimeCraft Files from System Registry	16
7.0 Contacting Technical Support	19
Revision History	20
The Microchip WebSite	21
Customer Change Notification Service	21
Customer Support	21

1.0 KNOWN ISSUES AND WORKAROUND

This section lists the known workaround and the operating constraints, with and without the workaround.

Known Issues	Workaround
TimeCraft 2.6.5a is not able to connect to SSU 2000 7.3.1 version if existing TimeCraft version is upgraded with newer version.	Uninstall TimeCraft using windows “Program and Feature” option, and remove all residual files from “C:\Program Files (x86)\Microsemi\TimeCraft” and Install TimeCraft 2.6.5a.
On Windows 10 or Windows 8.1 TimeCraft 2.6.5a may not be able to connect to Legacy SSU 2000 COMM firmware’s.	Even after enabling “telnet client” feature on Windows 10 or 8.1, TimeCraft is not able to connect SSU 2000. To resolve this, follow below recommendation suggested by Microsoft and reboot windows PC. https://answers.microsoft.com/en-us/windows/forum/all/windows-cannot-find-telnet-make-sure-you-typed-thea5ea2bdd-8c20-42a9-b3b4-0402b4e19769
A user newly created by TimeCraft could not access SSU-2000 with TimeCraft using the serial port.	Use Ethernet connection or Procomm or equivalent to set up user.
10848: PTP Client list from a PTP Blade in SSU-2000 is not displayed with TimeCraft 2.5 with SSU-2000 users level 2 and 3.	Use TL-1 or ICS commands to get PTP client list instead of TimeCraft.
10246: It is not possible to open a TimeCraft telnet session with Windows 7.	By default, Windows 7 does not enable telnet client utility. Users needs to turn on telnet features manually. Follow below instruction to enable telnet client utility on Windows 7: <ol style="list-style-type: none">1. Click Start, and then click Control Panel.2. On the Control Panel Home page, click Programs.3. In the Programs and Features section, click Turn Windows features on or off.4. If the User Account Control dialog box appears, confirm that the action it displays is what you want, and then click Continue.5. In the Windows Features list, select Telnet Client, and then click OK.
When a number of autonomous (AO) events/alarms are reported from the TimeHub system, TimeCraft will temporarily suspend activity retrieving NTP/PTP card information. Once the autonomous outputs have stopped, TimeCraft will recover from the suspended state.	Wait until all the autonomous events/alarms from TimeHub have stopped. TimeCraft will retrieve the required user data after recovering from the suspended state. This may take a few minutes.
SSU 2000 6.2—After opening the connection, the SNMP v2 and v3 manager information is displayed incorrectly.	Click Refresh to update the SNMP v2/v3 manager details.
SSU 2000 6.2—While restoring the incorrect configuration file, the “Restore Successfully” TimeCraft prompt displays.	—
On the Help page, printing cannot be cancelled by clicking the Cancel button.	—
The SSU 2000/2000e module’s removal or insert status is not shown properly.	To minimize this issue, manually refresh the module and avoid multiple removal and insertion cycles.

Known Issues	Workaround
23791: After TimeCraft is connected to an SSU 2000/2000e with a TCP/IP connection for a long period of inactivity (24 hours), TimeCraft is slow to update changes. However, the TL1 commands continue to work.	Restart TimeCraft so that response time returns to normal and commands are executed and updated quickly. If an open connection is needed for a long period of inactivity, use a serial port connection.
User may observe that TimeCraft is slow in connecting to the SSU 2000/2000e NE because the auto refresh interval is 1 minute by default.	Change the auto refresh interval to 5 or 10 minutes. Click on the System Configuration tree node, then click the Edit button in the Refresh panel to bring up the Edit Refresh Configuration dialog box. Change the Refresh Interval to 5 or 10 minutes, then click the OK button to finish.
The user may sometimes notice that TimeCraft does not appear to communicate with the SSU 2000 correctly.	Refresh the NE connection by clicking on the Refresh Connection menu item in the Connection menu.
During TimeCraft firmware legacy upload for SSU 2000/2000e, the module option “all” should only select all likely modules with related firmware. For example, all DS1 output modules should be selected when the firmware upload is 01700E00.dn1. However, the TimeCraft upload process will go through all modules in the shelf.	—
TimeCraft does not have option to configure output PQL.	Use CLI command (OUTPUT xAy PQL {0 {1-16}}) or use below appropriate. TL1 command to set output PQL: <ul style="list-style-type: none"> • SET-PRMTR-OUTPUT • SET-PRMTR-OUT422 • SET-PRMTR-OUTE1208 • SET-PRMTR-OUTSINE
Manufacturing Discontinued Products: <ul style="list-style-type: none"> • (OT-21) The SID is reported by the OT-21 in quotes even though quotes haven't been entered which is reflected by TimeCraft. A new SID should be entered without quotes. • (TSG3800) In the Security Window, pressing “Enable Security” requires closing the connection, editing the connection with login information, then connecting to the unit again. • (TSG3800) It is recommended that the information in the Help File be supplemented with information in the TSG3800 User Manual as in certain cases information in the Help File is brief. • (TSG3800, PRR10) In certain cases graphics are incomplete. • (PRR10) Parameters can be configured from the primary module only. • (TSG3800) 23823: No TSG-3800 serial port connectivity after user id is added. 	Use a TCP/IP connection.

2.0 SUPPORTED NETWORK ELEMENTS—SUPPORT MATRIX

The following table provides a list of the current supported hardware and firmware revisions. Refer to the System Release Notice (SRN) for firmware versions and compatibility for the product and particular release version you are using.

System	Versions
TimeProvider 1000/1100	1.0, 2.1, 2.2, 3.0, 3.1, 3.1.1, 3.2, 3.3, 3.4
SSU 2000	4.1, 4.2, 5.1, 6.0, 6.1.1, 6.2, 6.3, 6.4, 7.0, 7.1, 7.2, 7.2.5, 7.3, 7.3.1
TimeHub	R4209C, R4315C, R4328E, 3.2.2, 4.1.3, 5.0.5, 6.0, 6.1
TimeSource 3500/3000	1.06.06, 1.06.07, 1.06.10, 1.07.02, 1.07.04, 1.07.06
TimeSource 3600/3100	1.06.04, 1.06.09, 1.06.11, 1.07.05
ePRTC/TimeSource 3x50	1.0, 2.0, 2.1.1, 2.1.7

3.0 INSTALLING TIMECRAFT APPLICATION

Notes:


- Administrative privileges may be required to install this product.
- Please read this procedure and [Uninstalling TimeCraft Application](#) before attempting to install this release.
- TimeCraft 2.3, TimeCraft 2.4, TimeCraft 2.5 or TimeCraft 2.6 can be upgraded using TimeCraft 2.6.5. TimeCraft 2.6.5a is not upgradable for TimeCraft 2.6.5 or earlier versions. If earlier versions of TimeCraft (2.6.5 or earlier) exists on the target system, before installing TimeCraft 2.6.5a, save the connections folders and then ensure that all earlier versions of TimeCraft have been uninstalled.
- Follow the procedure for uninstallation in [Uninstalling TimeCraft Application](#).
- If TimeCraft 2.3, 2.2, 2.1, or 2.0 is to be re-installed for some reason, TimeCraft 2.6.5 must be uninstalled first. Refer to [Uninstalling TimeCraft Application](#). This helps avoid registry or directory conflicts due to known issues with the TimeCraft Installer.

Use the following procedure to install TimeCraft:

1. Insert the CD-media into the CD-ROM drive.
2. Open the CD-ROM folder and double-click on Setup.exe.
3. When the installer Welcome screen appears, click **Next**.



4. Click the **I accept the terms of the license agreement** radio button and then click **Next**.



a) SynCraft/TimeCraft Previous Version File Located:

If the Installer detects that a previous version of TimeCraft or SynCraft prior to version 2.2 is already installed, a message dialog appears stating that the application must be uninstalled before you can continue. Refer to the procedure [Uninstalling TimeCraft Application](#).

If the SynCraft or TimeCraft Installer can't be located in the programs list, please go to the directory C:\Program Files\Symmetricon\ (or any directory where TimeCraft/SynCraft was installed) and locate the TimeCraft/SynCraft folder(s). The folder should include a "TimeCraftUninstall.exe" file, which can be used to uninstall the directory. Double-click on the "TimeCraftUninstall.exe" file to run it.

If the "TimeCraftUninstall.exe" file can't be located, manually delete the TimeCraft/SynCraft folders by dragging them to the Recycle Bin. Then follow the procedure [Removing SynCraft / TimeCraft Files from System Registry](#) to remove the SynCraft/TimeCraft files from the system registry.

b) TimeCraft 2.2 or later is present:

If the Installer detects that a previous version of TimeCraft or SynCraft later than or including version 2.2 is already installed, a message dialog appears prompting you to upgrade.


c) TimeCraft 2.6.5 Already Present:

If the installer detects that TimeCraft 2.6.5 is already present on the system, the following screen appears. Click the radio button for the appropriate task: Modify, Repair, or Remove. Click **Next** and follow the instructions on the screen.


5. Click the radio button for the appropriate task: Modify, Repair, or Remove. Click Next and follow the instructions on the screen.




- Click **Browse** to navigate to a desired directory, or click **Next** to install TimeCraft in the default directory. The default directory is "C:\Program Files" on 32 Bit OS and "C:\Program Files (x86)" on 64 bit OS and the installer automatically creates the \Microsemi\TimeCraft directory.




- Click **Install** to continue.



-
8. During installation, a status bar indicates the installation progress.



9. Select the Enable Advanced Security radio button, or the Disable Advanced Security radio button to enable or disable advanced security. If advanced security is enabled, the user is required to provide a user-name and password with each attempt to open a connection to a device. If advanced security is disabled, this information is stored on the computer so the user does not need to enter the user-name and password with each attempt to open a connection to a device. Then click the **Next** button.



-
10. The InstallShield Wizard Complete screen appears when the installation is finished. Click the **Finish** button.



Note: After upgrading an existing installation of TimeCraft with 2.6.5 on Windows 7, copy the connection details which are stored in the user virtual store directory to the new installed location. The default directory is "C:\Program Files" on 32 Bit OS and "C:\Program Files (x86)" on 64 bit OS.

4.0 UPGRADING TIMECRAFT APPLICATION 2.3/2.4/2.5 OR 2.6 TO TIMECRAFT 2.6.5

This section describes how to upgrade the TimeCraft from version 2.3/2.4/2.5 or 2.6 to version 2.6.5.


Note: Upgrade to 2.6.5a is not supported in this release. Remove/uninstall existing TimeCraft and install 2.6.5a release.

Use the following procedure to upgrade TimeCraft 2.6.5:


1. Insert the CD-media into the CD-ROM drive.
2. Open the CD-ROM folder and double-click on Setup.exe.
3. When the upgrade confirmation dialog appears, click **Yes**.




4. When the installer Resume screen appears, click **Next**.



5. During upgrade, a status bar indicates the upgrade progress.



6. The InstallShield Wizard Update screen appears when the update is finished. Click the **Finish** button.



Note: After upgrading the existing TimeCraft application with 2.6.5 on Windows 7, copy the connection details which are stored under the user virtual store directory to the new installed location. The default directory is "C:\Program Files" on 32 Bit OS and "C:\Program Files (x86)" on 64 bit OS.

5.0 UNINSTALLING TIMECRAFT APPLICATION


Note: Before you uninstall either SynCraft or TimeCraft, if you want to retain your list of connections make a copy of the connections folder located in the \Program Files\Symmetricom\SynCraft or \TimeCraft directory. Move the copy of the connections folder out of the application directory so that it is not deleted during the uninstall. After you install TimeCraft, copy the connections folder to the "C:\Program Files\Microsemi\TimeCraft" directory on 32 Bit OS or "C:\Program Files (x86)\Microsemi\TimeCraft" directory on 64 Bit OS. Ensure that all TimeCraft window are closed before uninstalling TimeCraft.

Use the following procedure to uninstall the applications associated with TimeCraft:


Note: Use the standard Windows procedure for uninstalling a program. This should be repeated individually for every program.

There are two methods for uninstalling TimeCraft 2.6.5a as shown in [Step 1](#) and [Step 2](#):


1. Users can uninstall TimeCraft 2.6.5 by clicking "setup.exe" from the CD-ROM and choosing the **Remove** option in the TimeCraft Maintenance window and by clicking **Next**, then continue with [Step 3](#); **OR** proceed with [Step 2](#).



2. From the **Start** menu, select **All Programs->Symmetricom->TimeCraft->UnInstall TimeCraft**. Then continue with [Step 3](#).
3. In the InstallShield Wizard screen, click **Yes** to remove the application and all features.



-
- When the uninstall is complete, click **Finish**.



- Repeat these steps to remove any other installed applications.
- Ensure the \Program Files\Symmetricon or \Program Files\Microsemi directory is empty after uninstallation. If a TimeCraft/Syncraft directory remains, open it. The directory should include a "TimeCraftUninstall.exe" file, which can be used to uninstall the directory. Double-click the "TimeCraftUninstall.exe" file to run it.
- If you can't locate the "TimeCraftUninstall.exe" file, manually delete the TimeCraft/SynCraft folders by dragging them to the Recycle Bin.

Note: On Windows 7, after uninstalling TimeCraft some application files may still be present in the virtual store directory. This may cause TimeCraft to "remember" settings from a previous installation which has already been uninstalled. Therefore, for a clean uninstall, open the C:\Users\User_name\AppData\Local\Virtual-Store\MyApp folder, and then delete any obsolete application data.


6.0 REMOVING SYNCRAFT / TIMECRAFT FILES FROM SYSTEM REGISTRY

Cautions:


- Microchip recommends that the following procedure only be performed by Network/PC System Administrators.
- Be very careful when removing SynCraft or TimeCraft files from the registry. Please follow the instructions below very closely and carefully. Microchip is not responsible for any unintended deletion of registry files.
- If you have any questions or concerns about this procedure, please call Microchip for assistance. See [Contacting Technical Support](#).

Use the following procedures to remove the SynCraft / TimeCraft Files from System Registry:


1. Click the **Start** button and select **Run**.




2. Type in "regedit" and then click the **OK** button.




- a) The Registry Editor window appears.




3. Select **My Computer** from the left tree. Then select **Find** from the **Edit** menu (**My Computer** > **Edit** > **Find**).



4. Enter "SynCraft" or "TimeCraft" in the "Find what" field. Click the **Find Next** button and wait for the search result.



- Caution:** Be very careful when selecting SynCraft or TimeCraft files and deleting them from the registry. Microchip recommends that this process only be performed by Network/PC System Administrators. Microchip is not responsible for any unintended deletion of registry files.



7.0 CONTACTING TECHNICAL SUPPORT

If you encounter any difficulty installing the update or operating the product, contact Microchip Frequency and Time Division (FTD) Services and Support at:

U.S.A. Call Center:

Including Americas, Asia and Pacific Rim

Microchip FTD Services and Support

3870 N. First Street

San Jose, CA 95134

Toll-free in North America: 1-888-367-7966 (1-888-FOR-SYMM) Telephone: 408-428-7907

E-mail: ftd.support@microsemi.com

Internet: www.microsemi.com/ftdsupport

Europe, Middle East, and Africa (EMEA) Call Center:

Microchip FTD Services and Support EMEA Altlaufstrasse 42

85635 Hoehenkirchen-Siegersbrunn, Germany

Telephone: +49 700 3288 6435

Fax: +49 8102 8961 533

E-mail: ftd.emeasupport@microsemi.com

Internet: www.microsemi.com/ftdsupport

REVISION HISTORY

The revision history describes the changes that were implemented in the document. The changes are listed by revision, starting with the oldest publication.

Revision	Date	Description
A	09/2021	Initial Revision

THE MICROCHIP WEBSITE

Microchip provides online support via our WWW site at www.microchip.com. This website is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the website contains the following information:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

CUSTOMER CHANGE NOTIFICATION SERVICE

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip website at www.microchip.com. Under "Support", click on "Customer Change Notification" and follow the registration instructions.

CUSTOMER SUPPORT

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Field Application Engineer (FAE)
- Technical Support

Customers should contact their distributor, representative or Field Application Engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
 - Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
 - Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
 - Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is “unbreakable”. Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.
-

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at <https://www.microchip.com/en-us/support/design-help/client-support-services>.

THIS INFORMATION IS PROVIDED BY MICROCHIP “AS IS”. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP’S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer’s risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

For information regarding Microchip’s Quality Management Systems, please visit www.microchip.com/quality.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maxStylus, maxTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, QuietWire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, NVm Express, NVMe, Omniscent Code Generation, PICDEM, PICDEM.net, PICKit, PICTail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQL, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, Symmcom, and Trusted Time are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2021, Microchip Technology Incorporated and its subsidiaries.

All Rights Reserved.

ISBN: 978-1-5224-8974-0

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX
Tel: 512-257-3370

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Novi, MI
Tel: 248-848-4000

Houston, TX
Tel: 281-894-5983

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453
Tel: 317-536-2380

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608
Tel: 951-273-7800

Raleigh, NC
Tel: 919-844-7510

New York, NY
Tel: 631-435-6000

San Jose, CA
Tel: 408-735-9110
Tel: 408-436-4270

Canada - Toronto
Tel: 905-695-1980
Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733

China - Beijing
Tel: 86-10-8569-7000

China - Chengdu
Tel: 86-28-8665-5511

China - Chongqing
Tel: 86-23-8980-9588

China - Dongguan
Tel: 86-769-8702-9880

China - Guangzhou
Tel: 86-20-8755-8029

China - Hangzhou
Tel: 86-571-8792-8115

China - Hong Kong SAR
Tel: 852-2943-5100

China - Nanjing
Tel: 86-25-8473-2460

China - Qingdao
Tel: 86-532-8502-7355

China - Shanghai
Tel: 86-21-3326-8000

China - Shenyang
Tel: 86-24-2334-2829

China - Shenzhen
Tel: 86-755-8864-2200

China - Suzhou
Tel: 86-186-6233-1526

China - Wuhan
Tel: 86-27-5980-5300

China - Xian
Tel: 86-29-8833-7252

China - Xiamen
Tel: 86-592-2388138

China - Zhuhai
Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444

India - New Delhi
Tel: 91-11-4160-8631

India - Pune
Tel: 91-20-4121-0141

Japan - Osaka
Tel: 81-6-6152-7160

Japan - Tokyo
Tel: 81-3-6880-3770

Korea - Daegu
Tel: 82-53-744-4301

Korea - Seoul
Tel: 82-2-554-7200

Malaysia - Kuala Lumpur
Tel: 60-3-7651-7906

Malaysia - Penang
Tel: 60-4-227-8870

Philippines - Manila
Tel: 63-2-634-9065

Singapore
Tel: 65-6334-8870

Taiwan - Hsin Chu
Tel: 886-3-577-8366

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600

Thailand - Bangkok
Tel: 66-2-694-1351

Vietnam - Ho Chi Minh
Tel: 84-28-5448-2100

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4485-5910
Fax: 45-4485-2829

Finland - Espoo
Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching
Tel: 49-8931-9700

Germany - Haan
Tel: 49-2129-3766400

Germany - Heilbronn
Tel: 49-7131-72400

Germany - Karlsruhe
Tel: 49-721-625370

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Rosenheim
Tel: 49-8031-354-560

Israel - Ra'anana
Tel: 972-9-744-7705

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Padova
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Norway - Trondheim
Tel: 47-7288-4388

Poland - Warsaw
Tel: 48-22-3325737

Romania - Bucharest
Tel: 40-21-407-87-50

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Gothenberg
Tel: 46-31-704-60-40

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820