



July 9, 2010

CN Number: 1008

CN Level: Minor

Subject: Updated Programming and Functional Failure Guidelines

Dear Customer,

Actel has updated its *Programming and Functional Failure Guidelines* as follows:

- Updated programming guidelines to standardize sample sizes and to reflect current yields
- Added FlashPro4
- Added SmartFusion™
- Updated Silicon Sculptor Device Support
- Updated FlashPro3 Device Support

Actel recommends that you review the updated guidelines. Effective immediately, all new RMA requests for programming failures will be processed and approved based on these new guidelines.

The updated guidelines are posted on the Actel website:

[www.actel.com/documents/FA\\_Policies\\_Guidelines\\_5-06-00002.pdf](http://www.actel.com/documents/FA_Policies_Guidelines_5-06-00002.pdf)

If you have any questions, please contact Actel's Application Technical Support at [tech@actel.com](mailto:tech@actel.com) and/or Customer Service at [customer.service@actel.com](mailto:customer.service@actel.com).

Regards,

Actel