Actel®

November 2, 2005

PCN Number: 0515

PCN Change Level: Major

Subject: New Version of Silicon Sculptor Software for A54SX32 and A54SX16P

Dear Customer,

This notice is to inform you that Actel has released a new version of Silicon Sculptor
software v3.92.2 DOS/v4.55.2 WIN. This version should be used when programming the
A54SX32 and A54SX16P devices. The products affected are listed in Table 1.

Table 1: Affected Devices

Device	Package	RoHS-Compliant
A54SX16P	PQ208	
A54SX16P	PQG208	✓
A54SX16P	TQ144	
A54SX16P	TQG144	✓
A54SX16P	TQ176	
A54SX16P	TQG176	✓
A54SX16P	VQ100	
A54SX16P	VQG100	✓
A54SX32	PQ208	
A54SX32	PQG208	✓
A54SX32	TQ144	
A54SX32	TQG144	✓
A54SX32	TQ176	
A54SX32	TQG176	✓
A54SX32	BG313	
A54SX32	BGG313	✓
A54SX32	BG329	
A54SX32	BGG329	✓
A54SX32	CQ208 *	
A54SX32	CQ256 *	

Note: * *Includes DSCC SMD Part Number: 5962-9958601QXC, 5962-9958602QXC,*
         5962-9958601QYC, and 5962-9958602QYC

This version of software will reduce the programming time on the above devices. This includes all temperature (C, I, M, and Class B) and speed grades (Std., –1, –2, and –3). Download the software at: http://www.actel.com/custsup/updates/silisculpt/sculptor3922.html. This software version and later versions should be used when programming the above devices.

For questions, please contact the Actel Technical Support hotline at tech@actel.com.

Regards,

Actel Corporation