Actel®

February 7, 2007

PCN Number: 0702

PCN Change Level: Minor

Subject: Silicon Sculptor v4.62.1 Release

Dear Customer,

Actel is pleased to announce the release of Silicon Sculptor software v4.62.1. This software release includes modifications that affect the MX product family. These modifications will improve programming for the entire MX product family: A40MX02, A40MX04, A42MX09, A42MX16, A42MX24, and A42MX36.

Failure to use this or a later version of Silicon Sculptor software may result in lower than expected programming yields. There is no impact to device reliability. The Silicon Sculptor software can be downloaded from http://www.actel.com/download/program_debug/ss/.

Actel recommends that you always use the latest version of the software during programming.

If there are any questions and to request qualification information, please contact Actel's Application Technical Support at tech@actel.com.

Regards,

Actel Corporation