March 5, 2013

PDN Number: 1301

Subject: New Revision of Silicon Sculptor Adapter Module Available
(SMPA-456BG-ACTEL-2)

Dear Customer,

This notice is to inform you that Microsemi SoC Products Group has been required to change the socket for a programming hardware adapter because the previous socket was obsoleted by the vendor. The replacement adapter module should function identically to the previous module. The impact on the user will be minimal as the module is exactly the same with the exception of the socket used.

Due to this change in hardware, the associated part number has been updated:

Table 1: Affected Part Number

Obsolete Part Number	New Part Number
SMPA-456BG-ACTEL-2	SMPA-456BG-ACTEL-3

We are no longer accepting orders for the obsolete part number and the new part number is available for ordering now.

Feel free to contact Microsemi SoC Products Group Technical Support at soc_tech@microsemi.com if you require any further information.

Regards,

Microsemi SoC Products Group

Microsemi Corporation
One Enterprise, Aliso Viejo CA 92656 USA
Within the USA: +1 (949) 380-6100 · Sales: +1 (949) 380-6136
Fax: +1 (949) 215-4996 · www.microsemi.com