

SPPS Release Notes 11.7 SP2

Table of Contents

1	Release Notes.....	3
1.1	Enhancements/New features	3
1.2	TCL Changes	4
1.3	HSM Module Firmware Revision	4
1.4	Thales nShield Revisions	4
2	Known Issues.....	4

1 Release Notes

This document highlights changes made to the SPPS solution since **11.7 SPA**.

1.1 Enhancements/New features

- Digital signature support has been added to U-HSM, M-HSM and Microsemi HSMs so that all files exchanged between HSM are digitally signed and verified. This allows HSM to verify the authenticity and integrity of the files being exchanged.
- Security improvements in bitstream generation.

1.2 TCL Changes

No SPPS related TCL commands have been modified.

1.3 HSM Module Firmware Revision

This release has been tested and verified on Thales HSM firmware revision 2.55.1

1.4 Thales nShield Revisions

This release has been tested and verified on Thales nShield revisions 11.62.00 and 11.70.00.

2 Known Issues

No new issues detected in this release.