



**Microsemi Corporation**

01/23/2014

**Change Notification No: CN1402**

**CN Change Level: Minor**

**Customer Notification Only –Action Required**

**Subject: HSTL15 and SSTL18 IO capability for MSIO and MSIOD**

**Description of Issue:**

**HSTL15 and SSTL18 IO standards are nonfunctional on MSIO and MSIOD IO types**

**Solution:**

Use a DDRIO type if you need to use these IO standards.

Libero 11.2 SP2 will check for IO standard usage on affected IO types and will set design to pre-compile state. (SAR 53620)

**Products Affected by this Change:**

**SmartFusion2 and IGLOO2 Devices**

Any projected dates in this notification are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, contact your local Microsemi Sales Office, the factory contact shown above, or your local distributor.

This Product/Process Change Notification is confidential and proprietary information of Microsemi, and is intended only for distribution by Microsemi to its customers, for customers' use only. It must not be copied or provided to any third party without Microsemi's prior written consent.