



May 14, 2010

Subject: Legacy Colorado Product Line Supplied from Microsemi-Scottsdale Division

Dear Valued Customer:

This correspondence is official notice communicating the discontinuance of our Legacy Colorado Product Line now manufactured by the Microsemi-Scottsdale Division. Please note that the part numbers below are being impacted effective May 14, 2010. Product is subject to a last time buy, as outlined under the New Orders heading.

### **Part Numbers Being Discontinued**

See Appendix A for parts list. Please note that customer-specific derivatives are included in this notice of discontinuance, but may not be specifically listed.

### **Sales Contacts**

|                                    |                  |              |
|------------------------------------|------------------|--------------|
| Inside Sales Representative:       | Tom Hamblin      | 480-941-9536 |
|                                    | Sharon Mewborn   | 480-941-6553 |
|                                    | Michele Niedrich | 480-941-6529 |
|                                    | Kim Lilly        | 480-941-6562 |
| Inside Sales Manager – Scottsdale: | Holly Snopko     | 480-941-6349 |

### **Open Orders**

All currently scheduled orders at the Microsemi-Scottsdale Division shall be delivered per the dates reflected in our Order Acknowledgment from the Microsemi-Scottsdale division.


## New Orders

For those products being discontinued, Microsemi extends a Last Time Buy ("LTB") offer to you. The LTB offer is effective as of May 14, 2010, and all LTB orders must be placed by July 1, 2010.

Delivery of these products must be taken upon completion of product build. All orders are non-cancelable, non-returnable, and may be non-replaceable. Warranty for these products is per Microsemi Corporation Standard Terms and Conditions with the exception that replacement may not be available.

The Microsemi-Scottsdale Division extends to you our sincere appreciation for your business. Please feel free to contact our referenced sales personnel if you have any questions.

Sincerely,



Holly Snopko  
Manager of Planning, Procurement,  
and Customer Service  
Microsemi-Scottsdale Division  
8700 E. Thomas Road  
Scottsdale, AZ 85251

**Part Numbers Being Discontinued, Eligible for Last Time Buy  
Appendix A**

| <u>Item Number</u> | <u>Item Number</u> | <u>Item Number</u> | <u>Item Number</u> | <u>Item Number</u> | <u>Item Number</u> |
|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| 652597             | EH10006Z1          | EHF12Z1            | ERL14B1            | K2180B1EB1         | USR15              |
| 860642             | EH10008Z1          | EHF14B1            | ERL16B1            | K2180Z1EB1         | USR150             |
| 860899             | EH10010Z1          | EHF14Z1            | ERL2B1             | KBPC3027           | USR180A            |
| 6520597            | EH10012Z1          | EHF16B1            | ERL4B1             | KBPC3047           | USR20              |
| 6520691            | EH15002Q           | EHF16Z1            | ERL6B1             | PBPC3067           | USR25              |
| 6520857            | EH15002Y           | EHF24B1            | ERL8B1             | SS0496             | USR30              |
| 6520911            | EH15004Q           | EHF24Z1            | G34100B1EB1        | SS0521             | USR35              |
| 6520961            | EH15004Y           | EHF2B1             | G34100Z1EB1        | SS0521AS           | USR40              |
| 6521139            | EH15006Q           | EHF2Z1             | G34120B1EB1        | SS0566AM           | USR45A             |
| 6521140            | EH15006Y           | EHF6B1             | G34120Z1EB1        | SS0596AS           | USR50A             |
| 6521198            | EH15008Q           | EHF6Z1             | G34160B1EB1        | SS0597             | USR60A             |
| 6521210            | EH15008Y           | EHF8B1             | G34160Z1EB1        | SS0597AS-2         | USR70A             |
| 6521225            | EH15010Q           | EHF8Z1             | G3420B1EB1         | SS0695AR           | USR80A             |
| 6521237            | EH15010Y           | EHS10B1            | G3420Z1EB1         | SS1057             | USS10              |
| 6521279            | EH15012Q           | EHS10Z1            | G3440B1EB1         | SS1083             | USS15              |
| 6521374            | EH15012Y           | EHS12B1            | G3440Z1EB1         | UFB2.5             | USS5               |
| 102881AJ           | EH15014Q           | EHS12Z1            | G3460B1EB1         | UFB5               | USS7.5             |
| 138985AU           | EH15014Y           | EHS14B1            | G3460Z1EB1         | UFB7.5             | VK227              |
| D2260              | EH150Y10           | EHS14Z1            | G3480B1EB1         | UFS10              | VK247              |
| D8523              | EH150Y12           | EHS16B1            | G3480Z1EB1         | UFS5               | VK267              |
| D8532              | EH150Y14           | EHS16Z1            | G37100B1EB1        | UFS7.5             |                    |
| D8539              | EH150Y2            | EHS2B1             | G37100Z1EB1        | US100A             |                    |
| D8548              | EH150Y4            | EHS2Z1             | G37120B1EB1        | US12               |                    |
| D8549              | EH150Y6            | EHS4B1             | G37120Z1EB1        | US120A             |                    |
| D8558              | EH150Y8            | EHS4Z1             | G37160B1EB1        | US15               |                    |
| DLSR106            | EH6002B            | EHS6B1             | G37160Z1EB1        | US150A             |                    |
| EF30FH16           | EH6004B            | EHS6Z1             | G3720B1EB1         | US18               |                    |
| EF30FH18           | EH6006B            | EHS8B1             | G3720Z1EB1         | US180A             |                    |
| EF30FH20           | EH6008B            | EHS8Z1             | G3740B1EB1         | US20               |                    |
| EF30LH16           | EH6010B            | EHY150Q10          | G3740Z1EB1         | US200A             |                    |
| EF30LH18           | EH6012B            | EHY150Q12          | G3760B1EB1         | US25               |                    |
| EF30LH20           | EH7502B            | EHY150Q14          | G3760Z1EB1         | US30               |                    |
| EF30LT16           | EH7504B            | EHY150Q2           | G3780B1EB1         | US35               |                    |
| EF30LT18           | EH7506B            | EHY150Q4           | G3780Z1EB1         | US40               |                    |
| EF30LT20           | EH7508B            | EHY150Q6           | K21100B1EB1        | US45A              |                    |
| EFFH16             | EH7510B            | EHY150Q8           | K21100Z1EB1        | US50A              |                    |
| EFFH18             | EH7512B            | ERF10B1            | K21120B1EB1        | US60A              |                    |
| EFFH20             | EH8002Z1           | ERF12B1            | K21120Z1EB1        | US70A              |                    |
| EFLH16             | EH8004Z1           | ERF14B1            | K21160B1EB1        | US80A              |                    |
| EFLH18             | EH8006Z1           | ERF16B1            | K21160Z1EB1        | USB10              |                    |
| EFLH20             | EH8008Z1           | ERF2B1             | K2120B1EB1         | USB2.5             |                    |
| EFTH16             | EH8010Z1           | ERF4B1             | K2120Z1EB1         | USB5               |                    |
| EFTH18             | EH8012Z1           | ERF6B1             | K2140B1EB1         | USB7.5             |                    |
| EFTH20             | EHF10B1            | ERF8B1             | K2140Z1EB1         | USR100A            |                    |
| EH10002Z1          | EHF10Z1            | ERL10B1            | K2160B1EB1         | USR12              |                    |
| EH10004Z1          | EHF12B1            | ERL12B1            | K2160Z1EB1         | USR120A            |                    |