

Microsemi Corporation, a Microchip company

October 30, 2018

Product Discontinuance Notification (PDN) No: PSDS120A181110

Subject: EOL (End-of-Life) Notification for VRF148A, VRF148AMP

Description: Microsemi Corporation (MSC) is announcing the discontinuance of product(s) that are currently being offered by Microsemi Discrete and Power Management Group (DPM). The products affected by this PDN will no longer be available from Microsemi.

Reason for Discontinuance: The product(s) are being discontinued due to the closure of the Bend fab where these products are made.

Customer Impact: It may be necessary to adjust backlog quantities based on availability.

Replacement Parts: None

Last Order Date: March 31, 2019

Last Shipment Date: September 30, 2019

Products Affected by this Discontinuance: VRF148A, VRF148AMP

Contact Information:

If you have any questions concerning this change please contact your regional Microsemi Sales person:

http://www.microsemi.com/salescontacts

Regards,

Microsemi Corporation, a Microchip company

Any projected dates in this notification are based on the most current product information at the time this PDN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and

1

Microsemi Corporation
One Enterprise, Aliso Viejo CA 92656 USA
Within the USA: +1 (949) 380-6100 · Sales: +1 (949) 380-6136
Fax: +1 (949) 215-4996 · www.microsemi.com



any other information, please contact your local Microsemi Sales Office, the factory contact shown above, or your local distributor.

This PDN is confidential and proprietary information of Microsemi and is intended only for distribution by Microsemi to its customers, for customers' use only. It must not be copied or provided to any third party without Microsemi's prior written consent.

MSC part number	Description	Package	Potential Alternatives
VRF148A	RF Power Vertical MOSFET	M113	None
VRF148AMP	RF Power Vertical MOSFET, Matched Pair	M113	None
	1	1	