

July 26, 2010

CN Number: 1006

Re: Important ProASIC PLUS® Reminders

Dear Valued Customer,

Actel would like to take this opportunity to remind our customers that are using ProASIC PLUS (APA) devices that a configuration loss can occur over time if devices are operated outside of the voltage conditions specified in the datasheet.

Actel has taken, and will continue to take, steps to improve margin to this overstress-induced phenomenon.

We recommend that you always operate ProASIC PLUS devices within the voltage conditions specified and use the latest release of Libero Integrated Design Environment (IDE) software (currently 9.0 SP1) when designing or programming Actel ProASIC Devices.

If you have any questions, please contact your Actel sales representative.

Regards,

**Actel Corporation**