



January 24, 2005

PCN number: 0405

PCN change level: Minor

Subject: Marking Change for Automotive Temperature Devices

Dear Customer,

This notice is to inform you that Actel is making a minor change to the marking on its automotive devices. Currently the mark for automotive devices, designated by an "A", is located on the third line of the device. This mark is right after the package information. Effective immediately Actel may ship product either marked as described above, or with the automotive "A" mark, located in the top right hand corner of the package.

If there are any questions please contact Actel's technical support hotline at [tech@actel.com](mailto:tech@actel.com).

Regards,  
Actel

**Actel Corporation**  
2061 Stierlin Court  
Mountain View  
CA 94043-4655

Tel 650.318.4200  
Fax 650.318.4600

[www.actel.com](http://www.actel.com)



**Actel**

**A**

**AXXXXXA - ##**

**PK###Z YYWW**


**AAAAAA BBBB**

**BLANK LINE 1**

**BLANK LINE 2**

**BLANK LINE 3**

**COUNTRY**





# **Actel**

**AXXXXXA - ##**

**PK###A YYWW**

**AAAAAA BBBB**

**BLANK LINE 1**

**BLANK LINE 2**

**BLANK LINE 3**

**COUNTRY**

