



June 17, 2008

PDN number: 0804

PDN change level: Minor

Subject: Product Discontinuation Notice for BG329 DAISY CHAIN, FG256 DAISY CHAIN, FG484 23X23 DAISY CHAIN, FG484X79 23X23 DAISY CHAIN, and CG624 DAISY CHAIN BAE

Dear Customer,

This letter is to inform you of Actel's decision to discontinue five daisy chain products, effective immediately. The affected part numbers are shown in Table 1 below. The CG624 Daisy Chain, with solder column attach from BAE, is replaced by Six Sigma. The column attach will now only be sourced from Six Sigma. For future requirements where no replacement part number is listed, please source directly from the vendor, Practical Components.

**Table 1: Obsolete and Replacement Part Numbers**

Obsolete Part Number	Replacement Part Number
BG329 DAISY CHAIN	NA*
FG256 DAISY CHAIN	NA*
FG484 23X23 DAISY CHAIN	NA*
FG484X79 23X23 DAISY CHAIN	NA*
CG624 DAISY CHAIN BAE	<b>CG DAISY CHAIN SIX</b>

\*Practical Components: <http://www.practicalcomponents.com/index.htm> 714-252-0010

For questions or concerns regarding this matter, please contact your local Actel Sales representative or your regional FAE for assistance.

Regards,

Actel