



Microsemi Corporation

November 6, 2013

Product Discontinuance Notification (PDN) No: PDN1307

Subject: SmartFusion2 Development Kit (SF2-DEV-KIT-PP-1)

Description:

Microsemi is announcing the discontinuance of the SmartFusion2 Development Kit with PP silicon (SF2-DEV-KIT-PP-1), due to a new revision of the board having been developed to support Power over Ethernet to go along with the production silicon.

Reason for Discontinuance:

We now have the Power over Ethernet function working properly along with the production silicon.

Customer Impact:

Customers will be receiving the production silicon and working Power over Ethernet on the development kits. The old PP-1 development kit will be phased out once the remaining stock of SF2-DEV-KIT-PP-1 has been depleted. There are no other changes to the board and it will function identically to the original kit

Replacement Parts: SF2-DEV-KIT is the new part number for SmartFusion2 Development Kits.

Products Affected by this Discontinuance: SF2-DEV-KIT-PP-1

Old Part Number	New Part Number
SF2-DEV-KIT-PP-1	SF2-DEV-KIT

Contact Information: Microsemi SoC Products Group

Should you have any questions, please contact your Microsemi SoC Corp. Sales Representative.

Regards,
Microsemi Corporation

Any projected dates in this notification are based on the most current product information at the time this PDN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Microsemi Sales Office, the factory contact shown above, or your local distributor. This PDN is confidential and proprietary information of Microsemi and is intended only for distribution by Microsemi to its customers, for customers' use only. It must not be copied or provided to any third party without Microsemi's prior written consent.

Microsemi Corporation
One Enterprise, Aliso Viejo CA 92656 USA
Within the USA: +1 (949) 380-6100 - Sales: +1 (949) 380-6136
Fax: +1 (949) 215-4996 · www.microsemi.com

PDN1307-1/11.13

Obsolescence Notice