



## Microsemi Corporation

January 20, 2014

**Product Discontinuance Notification (PDN) No: PDN1401** 

Subject: Silicon Sculptor Adapter Module SM896FG-ACTEL

## **Description:**

Microsemi<sup>®</sup> is announcing the discontinuance of hardware programming adapter module - Silicon Sculptor Adapter Module (SM896FG-ACTEL). The replacement adapter module SMAX-896FG-ACTEL should function identically similar to the previous module.

#### **Reason for Discontinuance:**

The version, SM896FG-ACTEL, is phased out by the vendor.

## **Customer Impact:**

The impact on user will be minimal as the module functionality is exactly the same with an exception of the socket used.

Replacement Parts: SMAX-896FG-ACTEL is the new part number for SM896FG-ACTEL

Products Affected by this Discontinuance: SM896FG-ACTEL

Old Part Number	New Part Number
SM896FG-ACTEL	SMAX-896FG-ACTEL

Contact Information: Microsemi SoC Products Group

Should you have any questions, please contact your Microsemi SoC Corp. Sales Representative.

# Regards,

Microsemi Corporation

Any projected dates in this notification are based on the most current product information at the time this PDN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Microsemi Sales Office, the factory contact shown above, or your local distributor. This PDN is confidential and proprietary information of Microsemi and is intended only for distribution by Microsemi to its customers, for customers' use only. It must not be copied or provided to any third party without Microsemi's prior written consent.

Microsemi Corporation

One Enterprise, Aliso Viejo CA 92656 USA Within the USA: +1 (949) 380-6100 · Sales: +1 (949) 380-6136

Fax: +1 (949) 215-4996 · www.microsemi.com

PDN1307-1/11.13