

Microsemi Corporation

April 30, 2014

Customer Notification No: 1409A Customer Advisory Notice (CAN)

Subject: Defective power supplies have been shipped with a few of the M2GL-EVAL-KITs

This is an Addendum to CN1409.

Dear Customer,

Our records show that a few of the power supplies shipped with M2GL-EVAL-KIT, between September 2013 and March 2014, may be imperfect. The power supply may either fail to power up the board or the connector may not fit into the board correctly.

Our data shows that only a very small percentage of the power supplies are affected by this issue.

If you have received one of the defected power supplies, notify Microsemi SoC at: RMA@microsemi.com to have a replacement sent to you.

Contact Information:

Microsemi SoC Products Group

For any clarifications or questions, contact Microsemi SoC Tech Support.

Technical Support

Web: www.microsemi.com/soc/mycases

Phone (NA): 800.262.1060 Phone (Int'l): +1 650.318.4460 Email: soc tech@microsemi.com

Regards,

Microsemi

This Customer Notice (CN) or Customer Advisory Notice (CAN) are confidential and proprietary information of Microsemi and is intended only for distribution by Microsemi to its customers, for customers' use only. It must not be copied or provided to any third party without Microsemi's prior written consent.